PUBLIC WORKS. 1: 326. C.S. (Point William Light) SHI/NAV/1 # 13 No. SUBJECT. Col. Engineer. "L" 192 8 MAINTENANCE OF POINT WILLIAM LIGHT IIth March. 1926. Previous Paper. 108/25. MINUTES. 1 Minute from Col. Engineer of. 11 March. 1926. Glop for landom hum stamed to addend if then ar to span pans. 13 March 4416 13/3/26 The Hon: Colonial Secretary. Subsequent Paper. Noted. Dealt wit 2. Draft indent for panes and fit ingsalso Indent in In. quadruplicate submitted herewith for approval and Bransasely C.E. 21/4/26. forwarding.

No	
-	ì

(It is requested that, in any reference to this letter, the above Number and the date may be quoted. MINUTE.

IIth March 1926. 19

SUIL SECRETARY'S OF TO SELANDS *

From The Colonial Engineer.

Letter, "L",

THE COLONIAL SECRETARY,

Stanley, Falkland Islands.

I beg to report that I visited the Point William Light on the I st March and put the new sunvalve on service. The light is now in good order.

- 2. The pattern of mantle of the new sunvalve is not the same as the original one supplied consequently the spares now in hand will not fit.

 The new pattern is an improvement on the old being provided with means for ventilation.
- Two panes of lantern house are cracked and will have to be renewed in the near future.

Ool; Engineer. II/3/26.