PPL/DTH/1#8 IEGAL C.S. 1924. (Miscellaneous) 390/24 No. CE. "L" SUBJECT. Coroner 192 4 DONALD J. MCASKILL 2na June, Respecting Coroners inquest on body of: Previous Paper. MINUTES. MINUTES. de 2nd June 1924 - Encl () PA 20 6/27 Starbur backs Refuses for your observations flease Title 5 June 1524 Stan. Lool. Stere Sary-The crew of H.M.C. S. Afterglaw live an board the vessel, being granted brave of absence, by the Master. The Gunner , The Engineer live permanently on board, ጌ. and are seldon absent from the Vessel after night fall. The Dockyard Pares are locked by the Police Every 3. Evening, being opened in the morning prior to working hours -Would respect fully submit that a Watchin an on board the Aiterglais has not appeared necessary but would beg to suggest that a lamp post with a good lamp, to be lighted each Evening at Sunset, be ErectEd on the Government Jetty at the Subsequent Paper. Extreme North End of Stone work. Colin & Hackly. Marbour master. 7. June 1934

4.5. Submitted that no mecenity has been shown for the appointment of a watchman and that C.S. be asked to report a thet this regula for impring the hipping till 10 fine 24 CS.

title 11 fren 20

The Hon. Col. Secy.,

With regard to a light on the Dockyard Jetty; I would suggest that when the AFTERGLOW is alongside a gangway lantern be lit every night, as the chief danger is when crossing from jetty to vessel. Further that an old puttern street lamp, with duplex burner, be placed to the east of the shed on the hulk, on the roof of the lean-to; the lantern to be fitted with a red sector on the south side and to be so adjusted as to show red when if a vessel, approaching from the eastward, were steering inside the jetty. This would, I think, be of great assistance to the crew of the "Penguin", especially on datk nights: The light to be lit when the "Penguin" is ruming at night and to be lit by one of the crew. Should anyone (i.e. passengers) be desirous to return to the mail boat the light would be an indication that there was still a launch running and a possibility of getting off if the reason for going were considered to be of sufficient importance.

pro-asely.

Colonial Engineer. 16/6/24.

C.S.O. No. 390/24

Inside Minute Paper.

Sheet No. Harbour hearter Have yn any Aberrahin b make in the detailed priforal? Att 17 Jun 24 Hou level. Secretary. Submit. Iwould concer with described proposal. Colin E. Hockly. Itarbour Master Publicher for affroral An 20 Sun 1924 C.S. accordingly The H'n; Col; Secretary. Noted. 2. Work will be put in hand as soon as possible. annarely. Colonial Engineer. 5/7/24. S will you flear refail from

· ··· Statt Stay, 24

B.U. 5- 18/24

The Hon; Col; Secretary.

Gangway light is lit when the

"Afterglow" is alongside jetty.

2. The new light on shed has not yet been fixed, it is hoped that it can be done next week.

Annasely. Colonial Engineer.

7/8/24.

Ch. Has this lowk have been Carfleter ! It will be useful when the chineses is is harbour

Attill 15 aug. 24

The Hon. Col. Secy.,

The light (Acetylene) has been erected It was tested on the evening of the 3rd of October, with satisfactory results. The jetty can now be approached by the launch with safety on dark nights , when the light is burning.

znos aselez.

Colonial Engineer.

U.S. To see Geliz Jorces. Jorces. M. 10 oct 424

B. L. 201081.

	UTE.
, (It is requested that, in any refer- ace to this minute, the above Number and the date may be received).	2nd.June 192419
From Ag. Coroner	То
2	THE COLONIAL SECRETARY,
	Stanley, Falkland Islands.

12

CORONERS INQUEST ON THE BODY OF DOHALD J.MCASKILL.

I am directed by the Chief Justice to transmit herewith an extract from the above Inquest :

Verdict. Found drowned.....

Rider added by Jury: A watchman should be appointed to the

H.M.C.S. "AFTERGLOW" while lying along-

the Pier.

- EouBBinn Coroner.