PUBLIC WORKS **UTI/POW/1#8** (Lamps and Lights) 1923. C.S. No. 434/23 SUBJECT. Col. Engineer 192 3 Col. Engineer reports interference with 19th June, Street Lamps. Previous Paper. MINUTES. Munute from Col Engeneer of 19th June 1928 . Cuel () Chiel Canstatte for your report please. It is rumanied that certam householden have lately been subjected to annoy once through malicions intel erence with their protorby. Will your please say whether comblamts have been received and if anything known of the offenders. GREL # Dicksu 4 June 1923 Subsequent Paper. over W. & S. Ltd.

How bol suretary There has been no complaints from honscholders, on the night in question her. Robsons set gate was unhinged two nights previous to that two Inskeys was stolen from Mer Robson He latter has recutly been found midden in the peak boy. The offenders are suspected known to the Police, but unfortunally up to the present the Police are not in possession of sufficient prof No Sullivan Chief boustable 7 July /23 1. Sabmitted GAR LA B DiClsec 7 July 1923. Att 9 July 1923.

FALKLAND ISLANDS.



C.S. No.....

LETTER FORM.

Departmental Number.

From The Colonial Engineer.

Date.19th. June., 1923.

.....

To The Hon. Col. Secretary.

SUBJECT.

Reporting interference with street lamps.

Reference Numbers.

The Hon, Col. Secy.,

I beg to submit the following report in reference to interference, by some person or persons unknown, with the street lamps.

Mr G. Perry (Lamplighter) reports that on the night 2. of the 15th. inst. at about 10-30 p.m. he extinguished the light at Waverley House. Constable Hooley informed Perry the following morning that this lamp was alight at II-30 the previous evening . The lamp remained alight until again extinguished by Perry on Saturday morning. On examination of the lamp it was found that the lamp glass and glass in lantern The lamp is being repaired and a door frame were broken. new glass supplied. I fear it will be acostly matter to keep this lamp in working order if this this the continues.

3. A few nights ago a I4' ladder attached to one of the Kitson Lampx posts was wrenched from the top carrying bar and thrown on to the adjoining fence, Considerable force was required to effect this damage, fortunately little damage was done to the lamp only the vapouriser being disarranged.

Colonial Engine r.