

C.S.

MEDICAL

UTI/WAT/1#4

1923

No. 832/23

Col. Surgeon

SUBJECT.

1923

Respecting taking of water from
Reservoir.

5th November

Previous Paper.

MINUTES.

Minute from Col Surgeon of 5th Nov 1923 — Encl ①

Colonial Engineer.

For your observations.

*G.M.H.
Di'c/sec
6 Nov^r 1923*

The Hon. Col. Secy.,

I think it will be found that the Harbour Master is the Officer in charge of the reservoir in front of Admiralty Cottage and has the keys of the gate and pump.

2. The plunger of the pump has been several times repaired; owing to the pump being so rarely used the leather plunger dries and cracks. I would suggest that a new semi-rotary pump be obtained for the reservoir.

R.N.S.-asely.
Colonial Engineer.

7/11/23.

Harbour Master.

For your observations.

*G.M.H.
Di'c/sec
9 Nov^r 1923*

Subsequent Paper.

Hon. Col. Secretary.

The lock of Reservoir Gate had been removed for overhaul.

Lock has been replaced & gate secured.

Col. C. Hodley
Harbour Master.

J.E. Submitted
G.R.H. 13
Dir/Sec
16 Nov 1923

Ask P.W.D. to send the key to me please if they have it now

19 Nov 23

Mr. Noye.

Will you please send key to H.E. as requested.

G.R.H. 13
Dir/Sec
20 Nov 1923

The Hon. Col. Secy.,

Key of reservoir gate herewith to be sent forward to His Excellency.

2. A duplicate key is held by the Harbour Master.

W. Noye
for Colonial Engineer.

21/11/23.

J.E. Submitted
G.R.H. 13
Dir/Sec
22 Nov 1923

The key is returned herewith.
 The Ch. informed us verbally
 some time ago that he was
 going to inspect the reservoir
 with a view to repairing a
 leak. Has he taken or
 is he taking any further action
 in this matter?

J.H.H. 1 Feb. 24

Colonial Engineer.

Referred
 G.R.H. 13
 D. Secy
 1 Feb 1924

The Hon; Colonial Secretary.

Key withdrawn.

2. Orders have been given to empty the reservoir
 and have it cleaned on Monday next. The top work
 will be examined and endeavour made to stop the
 leakage.

3. I should be glad to know if the expenditure
 is to be charged to the Port and Marine Department
 or to the P.W.D. If the P.W.D. to what Head and
 Sub-head please. ?

B. M. S. ascher

Colonial Engineer.

2/2/24.

Y.P. Submitted
 G.R.H. 13
 D. Secy
 2 Feb 1924

I inspected the Reservoir today
with the C.E.

The charges for repairs laid better
be against XVII 4

HULL 6 Feb. 24

Colonial Engineer

Referred

G.P. 13

Dir Secy

to Secretary

The Hon. Col. Secy.,

The reservoir was emptied on
the 4th inst., cleaned out and repaired.

2. As far as could be ascertained all the
cracks in the cement pointing were repaired and
it is hoped that the leakage has been stopped.

3. The reservoir is now filling.

R. M. S. S. S.

Colonial Engineer.

19/2/24.

G.P. Submitted

G.P. 13

Dir Secy

20 February 1924

HULL

25 Feb. 24

MINUTE PAPER.



Departmental Number. ,

From *Colonial Surgeon*

Medical

Date *5/11/23.*

To *Hon Col. Secretary*

SUBJECT.

Reference Numbers. }

I notice today a leak
dipping water out of the
reservoir in front of
Admiralty Cottage. This
is not only unsanitary, but
is most dangerous, as very
few people in this colony
are able to swim. Please

5/11/23.

J. H. Deane
Colonial Surgeon