

C.S.

LIVE STOCK

(Water Supply)

1924.

No.

7/24

Acting Stock Inspector

SUBJECT.

1924

GOVERNMENT LIVE STOCK

1st January

Respecting shortage of water supply

Previous Paper.

MINUTES.

*Minute from Acting Stock Inspector of 1st Jan 1924 — Encl (1)**Colonial Engineer.**For your observations please**E.P.H. 13
Dicks**2 Jan 1924**Minute from Acting Stock Inspector of 8th Jan 1923 — Encl (2)*

The Hon. Col. Secy.,

I have made enquiries and find that the sheds referred to are the back buildings and old stables at Sullivan House. To enable the roof catchment to be collected it will require new tanks and gutters as the present tanks are in very poor condition.

2. The pump will be examined and, if possible, repaired but I would like to state that ^{if} the water in this shallow well is too low to enable water to be drawn by means of a bucket then water pumped up will not be fit for drinking owing to sediment etc.; the foot of suction pipe should be at least 6" to 8" from the bottom of the well, otherwise the water will be polluted.

Subsequent Paper.

R. W. Massey
Colonial Engineer.
9/1/24.

29
Submitted
9/1/24
Oic/see
14 Jan 1924

I shall be glad to see a report on
the pump.

W.H.H. 15 Jan '24

Colonial Engineer.
Referred.
9/1/24
Oic/see
15 Jan 1924

The Hon. Col. Secy.,

The pump has been examined and the
barrel found to be cracked, also the working parts are
badly worn. The pump is practically beyond repair.
In the event of a pump being found to be necessary I would
suggest that a semi-rotary pump be ordered and that
arrangements be made when fixing same to protect it
from frost.

R. B. B. B. B.
Colonial Engineer.

21/1/24.

29
Submitted
9/1/24
Oic/see
21 Jan 1924

as Ch. Inspector to see Present requirements
can I think be met but later it will
certainly be desirable to renew the pump

W.H.H. 21 Jan '24



Stanley
1st January 1924.

The Honorable
The Colonial Secretary.

Sir,

I have the honor to inform you that the Stock Attendant reports a shortage of water, for the use of the Government Stock.

He says the water in the well is getting very low, I would suggest that this matter receive immediate attention, in the way of arranging that a supply be caught from the roofs of the buildings there.

I am, Sir

Your obedient Servant

W. G. Thomas
Acting Chief Inspector of Stock.



Starbuck
3rd January 1924.

The Honorable
The Colonial Secretary

Sir.
In continuation of my
conversation with His Excellency
yesterday, re. Shortage of Water
for the Government Stock,
I would ask that the pump
for use at the well at the
Government Stock Shed be put
in order as soon as it can
be conveniently arranged for.

I am, Sir,
Your Obedient Servant

W. Atkins
Acting Chief Insp. of Stock