

PUBLIC WORKS

(Drains)

1922

C.S.

No. 705/22

Governor

SUBJECT.

1922

Repair of Culverts near Sullivan House

12th October

Previous Paper.

MINUTES.

Minute from H.E. the Governor of 12th October 1922 ——— *End ①*

pa 29/10/22

C.S.

In immediate attention please

W. W. Noye

The Hon. Col. Secy.,

The broken pipes in the two culverts referred to by His Excellency and in three others farther to the west, which also were in a dangerous condition, have been removed and replaced by stone culverts.

Mud over two sound pipe culverts has been removed and a good layer of broken stones and shingle has been placed over them.

The track now appears to be safe.

W. W. Noye 101

Colonial Engineer.

17/10/22.

Subsequent Paper.

Yr. Subm. ited.
2. The P.W. D is to be compensated in the prompt manner in which the work was carried out. I had this up to visit the culverts and

Subject to what the result of heavy rains
might be the work seems to have been
well and satisfactorily done. The drainage
in the immediate vicinity of the culverts might
I think be improved by having the drains
cleared to carry the water into the main
ditch beneath the culverts

TTTTT 25/10/22

H.C.S.

The work appears when done satisfactorily
in the prompt manner in which it was
completed reflects credit on Mr. Pope & Mr. Bond.

2. The drains near the culverts should be
improved.

3. If labour can be spared the other culverts
along the Road should be put in order. In some
cases the holes should be better covered. Rough
stones should be covered + shingle added.

H.
26 Oct 1922

C.S. For note and action
TTTTT 26/10/22

The Hon. Coll Secy.,

Further repairs have been made and more stone and shingle placed over culverts.

2. Shortly after the above-mentioned culverts were repaired some person removed the side stones and blocked up the culvert with same. I have mentioned this to the Chief Constable.

3. Culverts farther along the track will receive attention as soon as circumstances will permit.

R. B. Basely.

Colonial Engineer.

7/12/22.

J.S.
Submitted for information

H.H.H. 22/12/22
R.
29 Dec 22

From Governor to Colonial Secretary.

About 80 yards beyond the slaughter house near Sullivan house there is a culvert which is in a dangerous condition: the pipes which were laid in 1920 have become exposed & are now rotten. I know that Mr. Baskley is off duty but I think Mr. Baskley could devise some means for improving matters: if he is unable to build a stone culvert it would be better to remove the pipes altogether.

2. A short distance further west the pipes ~~have~~ of another culvert have become exposed and are likely ^{soon} to become rotten & dangerous.
3. Any expenditure incurred can be charged to Head XIX Item 4.

4.

A.A.

12 Oct 1922